

Re: [TowerTalk] KT34A M2 Upgrade 15 meters Issue

I have collected some info on this topic thanks to several responders.

However, no one so far has claimed any experience with the M2 KT34A upgrade or the KT34M2.

M2 says there have never been issues with the 15 m F/B that they are aware of.

So LAST CALL, anyone out there using a M2 KT3x product ever had any issues with 15 m F/B. The particular units of interest are identified by a dimension between the 15 m reflector shorting bars of 46.75".

Once I collect any possible info here, a summary of the KT34 info found will be posted.

Thanks,

Bill, N6MW